REPORT DOCUMENTATION	ON PAG	iΕ		Form Approved			
Public reporting burden for this collection of information is estimated	atad ta ayaraga 1 h	our per response including t	no timo for roviouing inc	OMB No. 0704-0188			
maintaining the data needed, and completing and reviewing this	collection of inform Washington Head to that notwithstand	nation. Send comments rega quarters Services, Directorate ling any other provision of law	rding this burden estima for Information Operation on no person shall be sub	tte or any other aspect of this collection of information, including ons and Reports (0704-0188), 1215 Jefferson Davis Highway, Suite bject to any penalty for failing to comply with a collection of IDRESS.			
1. REPORT DATE (DD-MM-YYYY)	2. REPOI	RT TYPE		3. DATES COVERED (From – To)			
22 Jan 2013	Consulta	tive Letter		Sep 2012 – Jan 2013			
<b>4. TITLE AND SUBTITLE</b> 321 B North and PRL-S006 Verification S	urwaye at Ea	rmar McClallan AF	7D	5a. CONTRACT NUMBER			
Sacramento, CA	urveys at 10	inici Mecichan Ai	ъ,	5b. GRANT NUMBER			
				5c. PROGRAM ELEMENT NUMBER			
6. AUTHOR(S) Maj Alan Hale				5d. PROJECT NUMBER			
				5e. TASK NUMBER			
				5f. WORK UNIT NUMBER			
7. PERFORMING ORGANIZATION NAME(S) A USAF School of Aerospace Medicine		SS(ES)		8. PERFORMING ORGANIZATION REPORT NUMBER			
Occupational and Environmental Health D 2510 Fifth St.	ept/OEC			AFRL-SA-WP-CL-2013-0002			
Wright-Patterson AFB, OH 45433-7913							
9. SPONSORING / MONITORING AGENCY N.	AME(S) AND	ADDRESS(ES)		10. SPONSORING/MONITOR'S ACRONYM(S)			
				11. SPONSOR/MONITOR'S REPORT NUMBER(S)			
12. DISTRIBUTION / AVAILABILITY STATEM	ENT						
Distribution A: Approved for public relea	se; distributi	on is unlimited. Ca	se Number: 88	ABW-2013-0237, 22 Jan 2013			
13. SUPPLEMENTARY NOTES							
McClellan AFB, CA, from 12-13 Sep 12.	nt radiologic This verifica Survey (FSS) 2M Hill, con	cal assessment/verifation survey was co sampling. Radium ducted all radiologi	ication survey on ducted at each a-226 was the so cal field work to	of sites 321 B North and PRL-S006 at former of the sites post-remediation and after the ole radionuclide of concern. Environmental o include FSSs. This letter details the			
15. SUBJECT TERMS							
USAF School of Aerospace Medicine (US independent radiological assessment	AFSAM), fo	ormer McClellan Al	FB, radium-226,	, verification survey, final status survey,			
16. SECURITY CLASSIFICATION OF:		17. LIMITATION	18. NUMBER	19a. NAME OF RESPONSIBLE PERSON			
		OF ABSTRACT	OF PAGES	Col Mark E. Smallwood			
2 DEDORT   h ARSTRACT   6 T				40b TELEPHONE NUMBER (include area			

SAR

22

code)

U

U

U



#### DEPARTMENT OF THE AIR FORCE

## USAF SCHOOL OF AEROSPACE MEDICINE (AFMC) WRIGHT-PATTERSON AFB OHIO 45433

22 January 2013

MEMORANDUM FOR AFMSA/SG3PB

Attn: Maj Daniel Shaw USAF Radioisotope Committee Secretariat Air Force Medical Support Agency 7700 Arlington Boulevard, Suite 5158 Falls Church, VA 22042-5158

FROM: USAFSAM/OEC 2510 Fifth Street

Wright-Patterson AFB, OH 45433

SUBJECT: Consultative Letter, AFRL-SA-WP-CL-2013-0002, 321 B North and PRL-S006 Verification Surveys at Former McClellan AFB, Sacramento, CA

#### 1. Introduction:

a. *Purpose:* At the request of the USAF Radioisotope Committee Secretariat (RICS), the USAF School of Aerospace Medicine Consultative Services Division (USAFSAM/OEC) completed an independent radiological assessment/verification survey of sites 321 B North and PRL-S006 at former McClellan AFB, CA, from 12-13 Sep 12. This verification survey was conducted at each of the sites post-remediation and after the contractor had completed its Final Status Survey (FSS) sampling. Radium-226 (Ra-226) was the sole radionuclide of concern. Environmental Dimensions, Inc. (EDi), under contract with CH2M Hill, conducted all radiological field work to include FSSs. This letter details the findings of this visit and is meant to assist the RICS when evaluating the contractor's FSS reports of these sites.

#### b. Survey Personnel:

Maj Alan Hale, Chief, Radiation Health Consulting Branch, USAFSAM/OEC

- c. Personnel Contacted:
  - (1) Mr. Milton (Buddy) Walser, Radiation Program Manger, AFCEC/CIBW
  - (2) Mr. Philip Mook, Senior Representative, AFCEC/CIBW
- d. *Equipment*:
  - (1) Ludlum Model 2221, serial number 218606, calibrated on 23 Nov 11
  - (2) Ludlum Model 44-10, serial number PR276614, calibrated on 23 Nov 11

#### 2. Methodology:

a. *Background Area*. The background area of 400 m<sup>2</sup> has been routinely used as a reference area, since it has been determined to be radiologically nonimpacted. The background area was characterized with the 2x2 sodium iodide detector using a gamma walkover technique. No soil samples were taken in the background area, as the background soil concentrations for former McClellan AFB have been determined previously and were not relevant for this survey. After gamma walkover surveys at the survey sites, it was determined that the background area was not consistent with the survey areas, most likely due to the fact the background area still had vegetation in place. The background data are therefore irrelevant and are not presented.

b. *Survey Areas*. EDi was responsible for conducting a total of 17 FSSs across 17 different sites. The week of the visit, three sites were available for USAFSAM verification. After consultation with the RICS, two of these sites were chosen for verification survey: 321 B North and PRL-S006. The survey areas underwent gamma walkover surveys and soil sampling. This verification survey required at least 10% of the survey area to be scanned by the gamma walkover technique and soils sampling numbering at least 10% of the number taken by the contractor. Further information on the surveys can be found in Attachments 1-3.

- (1) Gamma Walkover Survey in Survey Areas. The goals of the walkover survey were to detail site radiological conditions, identify potential spots of elevated residual Ra-226 concentrations, and identify locations for biased soil sampling. Since the gamma walkover data were to qualitatively assess the site in terms of mean reading plus amount of standard deviation (SD), minimum detectable concentration and count rates were not calculated. Table 1 in section 3 summarizes the results of the gamma walkover survey.
- (2) Soil Sampling in Survey Areas. Since the contractor planned to collect less than 20 soil samples in each survey area, two biased soil samples were collected based on walkover data exhibiting elevated count rates. Each sample was taken from an area of about 8 in<sup>2</sup> to a depth of 6 in. The volume sampled was enough for laboratory analysis (approximately 0.25 gal). Field soil sampling procedures were in place to prevent cross-contamination of samples. Table 2, in section 3, summarizes the soil sample results.
- 3. Results. The results are summarized below along with some basic discussion. Additional substantiating data, including maps and survey data, can be found in Attachments 1-4.

Table 1. Gamma Walkover Results Summary

Survey Unit	Approximate Scan Coverage (%)	Mean Count Rate (cpm)	SD (cpm)	No. of Readings > Mean + 3 SD
321 B North	75	9182	550	3
PRL-S006	100	10777	862	0

Table 2. Soil Sampling Results Summary

Sample No.	Survey Unit	Ra-226 Concentration (pCi/g)	Ra-226 Concentration Uncertainty (pCi/g)
0GS0001	321 B North	0.890	±0.0417
0GS0002	321 B North	0.679	±0.0372
0GS0003	PRL-S006	0.794	±0.0427
0GS0004	PRL-S006	0.708	±0.0446

#### 4. Conclusions:

- a. All soil samples were taken in biased locations where the expected maximum Ra-226 concentrations were expected to be found. The maximum Ra-226 concentration was  $0.890 \pm 0.0417$  pCi/g. All the concentrations were less than the cleanup goal of 2.0 pCi/g, which is inclusive of background.
- b. Based upon the findings of this verification survey, USAFSAM finds that sites 321 B North and PRL-S006 are suitable for unrestricted free release of radiological controls, assuming the contractor reached the same results during its more comprehensive FSS.
- c. If these independent verification surveys are consistent with EDi's results, the RICS should have increased confidence in the contractor's FSS reports at all 17 remediated areas.
- 5. If you have any questions or need further information, please contact Maj Alan Hale at 937-938-3320 (DSN 798-3320) or alan.hale@us.af.mil.

ALAN C HALE, Maj, USAF, BSC Chief, Radiation Health Consulting Branch

an e. Hal

#### Attachments:

- 1. Instrumentation and Survey Methodology
- 2. Survey of 321 B North
- 3. Survey of PRL-S006
- 4. Laboratory Soil Analysis
- 5. Instrument Calibration Sheets
- 6. Radiation Meter Quality Control (QC) Log

#### INSTRUMENTATION AND SURVEY METHODOLOGY

- 1. Sodium Iodide Detector: The sodium iodide detector used was Ludlum 44-10 2x2-in detector coupled with a Ludlum 2221 Ratemeter/Scaler. For walkover surveys, the Ludlum 2221 was connected via cable to a Trimble GeoXT handheld GPS unit. The Trimble GeoXT logged the count rates with the corresponding GPS coordinates every 1 s. The detector was held at 10 cm above the ground for soil readings and walkover surveys. During walkovers, the scan speed was approximately 0.5 m/s. This is consistent with the methodology EDi used during gamma walkover surveys.
- 2. Laboratory Analysis of Soil. Soil samples were counted at the USAFSAM Radioanalytical Laboratory (OEAL) at WPAFB, OH. The soil was counted on a high purity germanium detector. The soils were also analyzed by OEAL using the appropriate in-growth method to determine Ra-226 levels in soil. Attachment 4 contains the laboratory reports.
- 3. All field instruments were function checked and field tested before and after use with check sources. All instruments were within a 25% tolerance during field checks. All instruments are calibrated on an annual basis at WPAFB, OH. Attachment 5 contains all annual calibration sheets, and Attachment 6 is the Radiation Meter QC Log.

#### **SURVEY OF 321 B NORTH**

1. Location. Figure A2-1 is a photograph of the 321 B North survey area.



Figure A2-1. Photograph of 321 B North

2. Survey Results. Two samples were taken in the 321 B North survey area. The gross Ra-226 soil concentration results, shown in Table A2-1, are inclusive of the background Ra-226 concentration and can be compared directly to the cleanup goal of 2.0 pCi/g. The locations of the soil samples are in Figure A2-2. The 321 B North survey area of approximately 380 m² was characterized with a sodium iodide detector using a gamma walkover technique. Scan coverage was approximately 75%. Due to the shallow nature of the excavation, only the floor of the excavation was scanned and did not include the side walls of the excavation. The resultant data of this walkover are found in Figure A2-3. Since there was a disparity in the mean count rates of the background survey area and the survey unit due to soil difference and through analysis of the statistics, the mean count rate of the survey unit itself and associated statistics were used as the "background" for this survey unit. The lowest readings of the survey are marked in green and correspond to less than 2 SDs above the mean background value. This green area is where soil concentrations are expected to be the lowest. The other colors represent areas of statistical significance, where higher concentrations are expected to be found. Yellow and red colors correspond to greater than 2 and 3 SDs, respectively, above the mean count rate value. The color

scheme demonstrates a scale of instrument data based upon SDs from background, where no regulatory values are implied.

Table A2-1. Soil Sample Results for 321 B North

Sample No.	GPS Coordinates (°N/°E)	Gross Ra-226 Concentration (pCi/g)
0GS0001	38.653394 / -121.403085	$0.890 \pm 0.0417$
0GS0002	38.653384 / -121.402969	$0.679 \pm 0.0372$




Figure A2-2. Soil Sample Locations for 321 B North



Figure A2-3. Gamma Walkover Data for 321 B North

## **SURVEY OF PRL-S006**

1. Location. Figures A3-1, A3-2, and A3-3 are photographs of the PRL-S006 survey area.



Figure A3-1. Photograph of PRL-S006, Overview



Figure A3-2. Photograph of PRL-S006, Viewed from Southwest



Figure A3-3. Photograph of PRL-S006, Viewed from Southeast

2. Survey Results. Two samples were taken in the PRL-S006 survey area. The gross Ra-226 soil concentration results, shown in Table A3-1, are inclusive of the background Ra-226 concentration and can be compared directly to the cleanup goal of 2.0 pCi/g. The locations of the soil samples are in Figure A3-4. The PRL-S006 survey area of approximately 40 m<sup>2</sup> was characterized with a sodium iodide detector using a gamma walkover technique. Scan coverage was approximately 100% of the excavation floor. Due to the deep nature of the excavation, the side walls of the excavation were also scanned, with a coverage of approximately 10%. The map has many points overlayed, since the GPS location uncertainty is on the order of 1 m, the site is small, and the side walls were scanned. The resultant data of this walkover are found in Figure A3-5. Since there was a disparity in the mean count rates of the background survey area and the survey unit due to soil difference and through analysis of the statistics, the mean count rate of the survey unit itself and associated statistics were used as the "background" for this survey unit. The lowest readings of the survey are marked in green and correspond to less than 2 SDs above the mean background value. This green area is where soil concentrations are expected to be the lowest. The other colors represent areas of statistical significance, where higher concentrations are expected to be found. Yellow and red colors correspond to greater than 2 and 3 SDs, respectively, above the mean count rate value. The color scheme demonstrates a scale of instrument data based upon SDs from background, where no regulatory values are implied.

Table A3-1. Soil Sample Results for PRL-S006

Sample No.	GPS Coordinates (°N/°E)	Gross Ra-226 Concentration (pCi/g)
0GS0003	38.654593 / -121.389503	$0.794 \pm 0.0427$
0GS0004	38.654629 / -121.389506	$0.708 \pm 0.0446$




Figure A3-4. Soil Sample Locations for PRL-S006



Figure A3-5. Gamma Walkover Data for PRL-S006

#### LABORATORY SOIL ANALYSIS

#### Sample Analysis Results Reported on 14-Nov-2012

USAFSAM/OBHHL ID 11200264 Customer Address 0117 Z 77 MDOS/SGPB 5342 DUDLEY BLVD

MCCLELLAN AFB CA 95652-1074

IDENTIFICATION

Base Sample # 0GS00001 Serial #

Date Collected 9/13/2012 Received 9/17/2012 Completed 11/7/2012

Analytes	Activity +/- Uncertanity	Lc / MDA
POTASSIUM 40	1.54E+01+/- 9.72E-01 pci/g	2.02E-01 / 4.27E-01 pci/g
RADIUM	8.90E-01 +/- 4.17E-02 pci/g	4.33E-02 / 8.90E-02 pci/g
THALLIUM 208	2.68E-01 +/- 3.33E-02 pci/g	2.24E-02 / 4.62E-02 pci/g
BISMUTH 212	8.84E-01 +/- 2.94E-01 pci/g	2.32E-01 / 4.83E-01 pci/g
LEAD 212	9.34E-01 +/- 5.26E-02 pci/g	3.00E-02 / 6.13E-02 pci/g
RADIUM 224	9.44E-01 +/- 3.32E-01 pci/g	2.75E-01 / 5.64E-01 pci/g
ACTINIUM 228	8.80E-01 +/- 7.54E-02 pci/g	8.03E-02 / 1.67E-01 pci/g
THORIUM 228	2.00E+00 +/- 7.66E-01 pci/g	1.17E+00 / 2.38E+00 pci/g
THORIUM 234	2.35E+00 +/- 8.43E-01 pci/g	1.05E+00 / 2.13E+00 pci/g
URANIUM 235	6.31E-02 +/- 3.26E-02 pci/g	2.64E-02 / 5.36E-02 pci/g

#### COMMENTS

WORKPLACE: 321 B NORTH

RA 226

RESULTS ACCURATE TO 2 SIGNIFICANT FIGURES. UNCERTANITY AT 95% CONFIDENCY LEVEL.

If you have any questions concerning the information provided above, please contact the ESOH Service Center at 1-888-232-2353.

#### Sample Analysis Results Reported on 14-Nov-2012

USAFSAM/OBHHL ID 11200266 Customer Address 0117 Z 77 MDOS/SGPB 5342 DUDLEY BLVD

MCCLELLAN AFB CA 95652-1074

#### IDENTIFICATION

Analytes	Activity +/- Uncertamity	Lc / MDA
POTASSIUM 40	1.58E+01+/- 9.84E-01 pci/g	2.13E-01 / 4.48E-01 pci/g
RADIUM	6.79E-01 +/- 3.72E-02 pci/g	3.97E-02 / 8.18E-02 pci/g
THALLIUM 208	2.67E-01 +/- 3.53E-02 pci/g	2.55E-02 / 5.22E-02 pci/g
BISMUTH 212	1.01E+00 +/- 3.11E-01 pci/g	2.40E-01 / 4.99E-01 pci/g
LEAD 212	9.07E-01 +/- 1.01E-01 pci/g	3.02E-02 / 6.16E-02 pci/g
RADIUM 224	5.71E-01 +/- 3.27E-01 pci/g	2.70E-01 / 5.54E-01 pci/g
ACTINIUM 228	8.49E-01 +/- 6.76E-02 pci/g	6.81E-02 / 1.42E-01 pci/g
THORIUM 228	9.28E-01 +/- 7.31E-01 pci/g	1.19E+00 / 2.43E+00 pci/g
THORIUM 234	2.59E+00 +/- 7.81E-01 pci/g	1.08E+00 / 2.19E+00 pci/g
RADIUM 226	1.57E+00 +/- 4.95E-01 pci/g	3.87E-01 / 7.87E-01 pci/g

#### COMMENTS

WORKPLACE: 321 B NORTH

RA 226

RESULTS ACCURATE TO 2 SIGNIFICANT FIGURES. UNCERTANITY AT 95% CONFIDENCY LEVEL.

If you have any questions concerning the information provided above, please contact the ESOH Service Center at 1-888-232-2353.

#### Sample Analysis Results Reported on 14-Nov-2012

USAFSAM/OBHHL ID 11200263 Customer Address 0117 Z 77 MDOS/SGPB 5342 DUDLEY BLVD

MCCLELLAN AFB CA 95652-1074

#### IDENTIFICATION

Base Sample # 0GS00003 Serial #

Date Collected 9/13/2012 Received 9/17/2012 Completed 11/7/2012

Analytes	Activity +/- Uncertanity	Lc / MDA
POTASSIUM 40	1.57E+01+/-1.03E+00 pci/g	2.33E-01 / 4.92E-01 pci/g
RADIUM	7.94E-01 +/- 4.27E-02 pci/g	4.22E-02 / 8.68E-02 pci/g
THALLIUM 208	2.67E-01 +/- 3.62E-02 pci/g	2.51E-02 / 5.18E-02 pci/g
BISMUTH 212	1.13E+00 +/- 3.61E-01 pci/g	2.76E-01 / 5.75E-01 pci/g
LEAD 212	1.06E+00+/- 1.21E-01 pci/g	3.62E-02 / 7.39E-02 pci/g
RADIUM 224	1.40E+00+/- 4.46E-01 pci/g	3.21E-01 / 6.59E-01 pci/g
ACTINIUM 228	9.95E-01 +/- 6.93E-02 pci/g	7.34E-02 / 1.54E-01 pci/g
THORIUM 228	1.70E+00 +/- 9.71E-01 pci/g	1.34E+00 / 2.72E+00 pci/g
THORIUM 232	1.64E+01 +/- 1.58E+01 pci/g	1.29E+01 / 2.62E+01 pci/g
URANIUM 235	7.08E-02 +/- 3.58E-02 pci/g	2.91E-02 / 5.92E-02 pci/g

#### COMMENTS

SEND RESULTS ALSO TO MAJ ALAN HALE DSN: 798-3320

WORKPLACE: PRL-5006

RA 226

RESULTS ACCURATE TO 2 SIGNIFICANT FIGURES. UNCERTANITY AT 95% CONFIDENCY LEVEL.

If you have any questions concerning the information provided above, please contact the ESOH Service Center at 1-888-232-2353.

#### Sample Analysis Results Reported on 14-Nov-2012

USAFSAM/OBHHL ID 11200265 Customer Address 0117 Z 77 MDOS/SGPB 5342 DUDLEY BLVD

MCCLELLAN AFB CA 95652-1074

#### IDENTIFICATION

Analytes	Activity +/- Uncertanity	Lc / MDA	
POTASSIUM 40	1.52E+01+/-9.77E-01 pci/g	2.23E-01 / 4.68E-01 pci/g	
RADIUM	7.08E-01 +/- 4.46E-02 pci/g	4.19E-02 / 8.59E-02 pci/g	
THALLIUM 208	3.56E-01 +/- 3.45E-02 pci/g	2.00E-02 / 4.14E-02 pci/g	
BISMUTH 212	1.07E+00 +/- 2.89E-01 pci/g	2.29E-01 / 4.78E-01 pci/g	
RADIUM 224	9.27E-01 +/- 3.20E-01 pci/g	2.70E-01 / 5.54E-01 pci/g	
ACTINIUM 228	1.12E+00 +/- 7.62E-02 pci/g	7.19E-02 / 1.50E-01 pci/g	
THORIUM 228	1.34E+00+/- 7.80E-01 pci/g	1.02E+00 / 2.09E+00 pci/g	
THORIUM 234	1.90E+00 +/- 8.45E-01 pci/g	1.06E+00 / 2.15E+00 pci/g	
URANIUM 235	6.99E-02 +/- 3.30E-02 pci/g	2.66E-02 / 5.41E-02 pci/g	

#### COMMENTS

WORKPLACE: PRL-5006

RA 226

RESULTS ACCURATE TO 2 SIGNIFICANT FIGURES. UNCERTANITY AT 95% CONFIDENCY LEVEL.

If you have any questions concerning the information provided above, please contact the ESOH Service Center at 1-888-232-2353.

## INSTRUMENT CALIBRATION SHEETS

Page 1 of 4



## DEPARTMENT OF THE AIR FORCE USAF SCHOOL OF AEROSPACE MEDICINE (AFMC) OCCUPATIONAL ENVIRONMENTAL HEALTH/RADIATION HEALTH (OEHH) WRIGHT-PATTERSON AFB OHIO

		CE	RTIFICAT	TE OF	CALIBR	ATION		
Mfg. Lud			Serial # 215					23 No. J 11
Mfg. Luc	II w MOO	lel <u>44-10</u>	Serial # FK 3	16614	_ index#_	008610	al. Due Date:	23 No. 1
	TEST	, MEASUREMEN	T AND DIAGN	NOSTIC E	QUIPMENT	r		
NIST 1	Fraceable C	heck Sources		Ref	ference Inst	ruments		
Isotope	Serial #	Cerl. Date	DPM	Mfg.	Model .	Serial #	Cal. Due D	ate
Cs-137	RP3067	1 Nov 04 2	,454,000	Ludlum	500-1	102951	8 Feb	2012
	protion facilities.	equipment used are to	,		of Standards and	l Fechnology, to the	extent allowed by	y the
	<b>√</b> Bath	ery Ck. Mechanic	ol Ck. Meter 2	Seroed	Reset Ck	NA Alarm	Ck.	
		V Audio Ck.	Geotro	pism Ck.	F/S Resp	Ck. Windo	w Op.	
As Four	aHV 991	VDC Tom	perature 7	127	°E 5	lafativa Messid	66	Dr.
		_			-	Relative Humid		%
Final Volt	Set 100	VDC Threshol	d (LLD) 10	m∨Wind	fow (ULD) g	LO_mV Win	dow width 🐰	mv
HV Rea	adout (2 poin	ts) Reference:	500 V		Refe	rence: 100	0 V	
	, , , , , , , , , , , , , , , , , , , ,	Inst. Readout:		+ 2%		edout: 100		4
						4		
	NGE	REFERENCE		FOUND"		RRECTED		
MULT	IPLIER	CAL. POINT	RE	ADING	R	EADING		
x 10	00	400 CPM	. 10011		CPM (	100,000		
x 10		100 CPM		000	CPM	100,000		
x 10	0	400 CPM		000	CPM	40,000		
x 10		100 CPM		000	CPM	10,000		
x 10		400 CPM		60 <i>0</i>	CPM	4,000		
x 10		100 CPM		000	CPM	1,000		
x1		400 CPM		DD	CPM	400		
X1		100 CPM		00	CPM	100	CPM	
Log Sca	nle	200 CPM		DD.	CPM	200	CPM	
			GITAL SCALE					
	REF. POINT		AS FOUND			CORRECTED		
	,000 CPM		39.886	CPM			CPM	
*UN	CERTAINTY	WITHIN ± 10%	JORKECTION	FACTO	K WITHIN ±	20%		
COMM C.S-A	ENTS: Ca	libration Interval =	Hyear Us	e "W 12 E la	indow D	LT'		
					Procedur	al Authority	- ICP#222	10000
brated By:_	550	Hutchin	5000			Date :	3 Nov 21	011
riewed By:_	Lips	Wal			_	Date:	30 <i>NoVII</i>	

Page 2 of 4



# DEPARTMENT OF THE AIR FORCE USAF SCHOOL OF AEROSPACE MEDICINE (AFMC) OCCUPATIONAL ENVIRONMENTAL HEALTH/RADIATION HEALTH (OEHH) WRIGHT-PATTERSON AFB OHIO CERTIFICATE OF CALIBRATION

Column   C	Cs-137 F  Measurement Sta leatitute's calibrat  Probe #1  Mfg	RP3067 Industries and test equicon facilities.  NaI DI	1 Nov 04 pulpment used new ETECTOR Fro	2,454,000 traceable to the Nati HIGH VOL	Ludlum onel Institute of	500-1	102951	8 Feb 2012
Measurement Standards and test equipment used are traceable to the National Institute of Standards and Technology, to the extent allowed by the Institute's calibration facilities.  NAI DETECTOR HIGH VOLTAGE OPTIMIZATION  Probe #1  Probe #2  Probe #3  Mrg.  Mrg.  Model  Model  Serial # PR 276614 Serial # Serial # Index # Inde	Measurement Stallastitute's calibrate Probe #1 Mfg	ndards and test of ion facilities.  Nat Di	pripment used see	traccable to the Nati	ional Institute of			
Nai DETECTOR HIGH VOLTAGE OPTIMIZATION	Probe #1 Mfg	NaI DI	ETECTOR:	HIGH VOL		Standards and	Technology, to th	
	High Voltage 750 800 850 900 950	DO861 -137 CPM	Ser Ind Iso	del#lope:High		Prob M/g. Mod Sent Inde	el #	:PM
		* /			-	-	-+	<b>─</b> ₩
1350 17910			VDC FI	nal Volt. Set	\ <sub>VD</sub>	C Fin	al Volt. Set	
135 0				ficiency	_ \		Efficiency	—— √ <sub>6 2π@%</sub>
Bkgd@ 1100 4669		500 CPWu		_	CPM/pol/m²			

Page3 of 4

## HotSpot FIDLER Text File Output HotSpot FIDLER Calibration Information

```
Report Date
                                                                     : Nov 23 2011 07:07 AM
                                                                           23 Nov. 2011
Other Nuclide Check Source
Cs-137
100861
  Calibration Date
 Target Mix
Radionuclide
 Detector Barcode Number
Méter Barcode Number
                                                                            099333
 Detector Manufacturer
Detector Model Number
Detector Serial Number
                                                                          Ludium
                                                                           PR276614
 Meter Manufacturer
Meter Model Number
Meter Serial Number
                                                                          Lud]um
2221
                                                                            218606
 Check Source I.D.
                                                                            RP 3067
Calibration Date :
Calibrated by :
Check Source Activity (uCi):
Check Source 17-keV Self :
                                                                           23 Nov, 2011
Stu Hutchinson
1.100E+00
1.000E+00
Sample Counting Time (minutes) : 1
Detector Height (cm) : 3.000E+01
 Cs-137 Window Information:
CS-137 Window Information:
Background (cpm)
Areal Limit of Sensitivity (uCi/m2): 4,669
Areal Limit of Sensitivity (uCi/m2): 4.9E-02
Point Limit of Sensitivity (uCi): 1.0E-01
K-factor (m2): 2.07
Counting Data (counts): 2.07
Counting Data (counts): 2.07
40-cm: 8120
20-cm: 7179
40-cm: 6081
60-cm: 5460
      60-cm:
                         5469
5167
      80-cm:
   100-cm:
Instrument Type :Other
Window Option:Only 60 keV
Units:Classic
This is an actual 2 x2 calibration and the values are typical of most 2 x2
 configurations.
Detector Calibration Results
Cs-137 Window Information:
Cs-137 Detector Efficiency (cpm/(uci/m2));
Cs-137 Detector Areal LOS (uCi/m2) :
Cs-137 Detector Point LOS (uCi) :
Cs-137 Detector Background Rate (cpm) :
Cs-137 Detector Check Source Rate (cpm) :
Cs-137 Detector K-Factor (m2) :
Cs-137 Detector K-Factor sdev (%) :
                                                                                                              4.9E-02
1.0E-01
4,669
3,451
2.07
7.5
```

Page 1

Cs-137 Eff: 6,500 CPM/NCV/m3@12"

Page 4 of 4

VDC	CS-137 CPM	DU Slug	Ludlum 2221	SN 218606		
			Ludium 44-10	SN 276614		
750	7834	7417				_
800	9969	10456				_
850	11523	13713				_
900	12240	16030				_
950	12771	16869				_
1000	12851	17336				_
1050	13589	17835				_
1100	13500	17515				_
1150	13697	17816				_
1200	13684	17764				_
1250	13908	17946				_
1300	13966	18133				_
1350	17910	18023				_
1400		18159	14			_
1450		19730				_
1500						_
1550						_
1600						_
25000						٦
20000					_	
15000					Cs-137 CPM	
10000					—— U-238 CPM —— Voltage	
5000	,				_	
0	0 800 9	900 1000 (1100	0 1200 1300 14	400 1500 1600		

## RADIATION METER QC LOG

#### **Radiation Meter QC Log**

Model	S/N	Date/Time	HV/cables/Bat check	Source Check Reading	Acceptable Range
2231 SPA 3	218600 PR276614	1050p@1335		21015 CBM	16812 - 25218 con
9831 SA3	78153 1R276615	1050@1337	/	2,818 cpm	17454 - 26181 com
3821 5143.	01860E 0R876614	125ep@1031	V	90109 com	16812 - 25218 cpm
20021 2003 2021	218606 RR276614	aspe 1152		19596 COM	16812-35318 cpm
8521 5113	218606 PR276614	125ep@1314	V	23 80 7 1 4 38 H	16812 - 25318 cps
SDA-3	218600 PR 276614	12500 150°	1	19258 cpm	16812 - 25218 <pm< td=""></pm<>
3921 5/133	318606 (R376614	135400 0948	V	19 708 cpm	16812 - 25218 cpm
8-281 58A-3	818606 PR 376614	13500 1135	V	19 689 cpm	16812 - 25218 CPM
		*	,		
			*		